ECS Configuration Change Quest Pages of / Pages					
CCR No. 98- 0/96 Logged Date 2/13/98		Rev. —	Request Type CCR		
Priority Routine	X Urgent	Emergency 🗌	Affected Release	Ver. 2	Change Class II
Title (description) LaRC Floor Plan					
Documents Affected	1		Source Nos (RID, I	NCR, Action It	em, EDC CCR, etc.) or
920-TDL-004 Pev: 3	T(NA		
RTM Change X Start New Baseline					
Problem Hardware at the LaRC DAAC has been moved due to reconfiguration of test bed hardware and upgrades to Version 2.0 hardware.					
Needed by February 18,	1998.				
Proposed Solution					
Changes have been mad	e to the attached floor	r plans that reflect the f	ardware changes that v	vere made at t	ile Larc DAAC.
Impact Analysis:				F00 [W.O. [7]
Organizations Affected: Procurement Science Off	800 Q0 X Security	Contracts	ECS Chief Eng	FOS	M&O ∑ SCDO Arch. ☐
Cost:	None	Small [Medium (\$100,000 to \$500,000)	Large (Over \$500,000)	
Schedule:	None	Other		***************************************	
Additional LOC			Man-Month	ıs	
Materials					
Originator Tim. Wells	ext. 4021	Timothy E. Wells Signature	Transley.	<u> </u>	18 2-13-98 Date
Office M&O	_ Office Manager	Tom Jaeger Signature	Sun les	Jon	2/13/98 Date
Disposition	Approved	Approved w/Comr	nent Forw	ard	Disapproved
Comments:	~	7	-//		12/98
	CCB Chairperson	Terry Fisher Signature	W fun	Key 2/	7 + / / C) Date

CM01OC96 ORIGINAL

cm est